

Information for item Damaged Ford

page 1



TITLE:	Damaged Ford
IDENTIFIER:	125-o1594_002
DESCRIPTION:	A photograph of a damaged Ford automobile, license plate #K 88125, at the Ford Garage in Rockford, MI The picture shows severe damage to the driver's side front quarter panel, tire, bumper, and a broken windshield and cracked side windows. The pictures was taken for the Michigan State Police, Rockford Post.
DATES:	November 26 1937 (Created)
SUBJECT HEADINGS (TGM):	Automobiles Garages Accidents
FILE IDENTIFIER:	125-o1594_002
SOURCE:	The Robinson Studio Collection (Coll. 125) - Grand Rapids History & Special Collections Department
PART OF DIGITAL COLLECTION:	Robinson Studio photographs